


# CleMate 110/120 Cleaning Stick



The CleMate 100 Cleaning Stick is designed for all optical fiber components inside the adapter or the receptacle.

The CleMate 100 offers two type diameter; 1.25mm and 2.5mm for different type of cleaning requirement. The easily usage makes the CleMate 100 can be using on any field. Just put the CleMate 100 in the adapter or receptacle and rotate the stick with slightly pressure, the particles inside the adapter will be removed.

## Specifications

Model	CleMate 110	CleMate 120
Cleaning Capacity	1 wipe	
Cleaning Size (mm)	1.25	2.5
Stick Length (mm)	100	100
Package	100pcs/box	

The Specifications are subject to be changed without notice.

## Ordering Information

**CleMate 110** — for 1.25mm Adapter/Receptacle

**CleMate 120** — for 2.5mm Adapter/Receptacle

